

ANNUAL SURVEYS.

31109

No. 118 Survey held at London Date Aug³⁰ 1870
on the Ship Newcastle Master C. G. French
Tonnage 1137 Built at Sunderland When built 1859
By whom built P. & S. Owners R. Green
Port belonging to London Destined Voyage Melbourne
If Surveyed Afloat or in Dry Dock Greens up Dock & aft

Last Survey, No. 30274 Port of Lon.

Classed 13. A. 1. H. T. / 69.
7. 69

The present Condition of the

Decks	good	Treenails where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	from the 2 ^d Sec
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors	No. of 3 & 1 S. 2 K
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Vales	"	Rudder efficient	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper for Vymu When put on 1869			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good

Survey'd in Ballast.
Sighted on account of reported leakage. found a hole left open behind one of the Rudder
braces, plugged it up, patched the yellow metal. I am of opinion she is entitled to remain as
Clas'd 13. A. 1.

Committee's Minute 16th September 1870

Character assigned

13 A 1

J. B. W.

Samuel Presnall
Sir Wm. W. W. W.
Certificate (if required)

No. 129 Survey held at London Date Aug⁷ 1870
on the Ship Swiftsure Master Shackford
Tonnage 1326 Built at United States When built 1854
By whom built — Owners R. & H. Green
Port belonging to London Destined Voyage Melbourne
If Surveyed Afloat or in Dry Dock Greens up Dock & East India Docks

Last Survey, No. 30554 Port of London

Classed S. S. / 66 4. A. 1. in red
12. 69

The present Condition of the

Decks	good	Treenails where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors	No. of 3 & 1 S. 2 K
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Vales	"	Rudder	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper for Vymu When put on 1869			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good

Survey'd in Ballast
Sighted the bottom. As far as seen she appears in good condition
and I am opinion is entitled to remain as clas'd

Committee's Minute 16th September 1870

Character assigned

13 A 1

J. B. W.

Certificate (if required).