

ANNUAL SURVEYS.

31/91

No. 177 Survey held at London Date 24th - 27th Oct^r 1870
 on the Barque "Persia" Master Peck
 Tonnage 530 Built at Scarborough When built 1838
 By whom built Lindall Owners Lindall & Co.
 Port belonging to Scarborough Destined Voyage —
 If Surveyed Afloat or in Dry Dock Carter's Dry Dock.

Last Survey, No. 29959 Port of Lon. Classed 12. C. 14.
AEI.
3, 69.

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>Good and</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers	} <u>where</u>	Keelsons	} <u>where</u>	Anchors No. of	} <u>complete</u>
Sheerstrakes		Clamps and Shelves		Cables	
Topsides	} <u>seen.</u>	Ceiling	} <u>seen.</u>	Hawsers and Warps	} <u>where seen.</u>
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>4. 11.</u> When put on <u>167.</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.
Yellow metal patched. New wire standing rigging to wiremast.
Is now in good and efficient condition, and fit in our
opinion to remain as classed - AEI. J. H. Eastlake.

Committee's Minute 1st November 1870

Character assigned A, 1

Certificate (if required).

No. 89 Survey held at London Date 28th October 1870
 on the Barque Jane Master Lindlay
 Tonnage 265 Built at Sunderland When built 1861
 By whom built Peverell Owners Brodie & Co.
 Port belonging to London Destined Voyage West-Indies
 If Surveyed Afloat or in Dry Dock Brodie's Dry Dock.

Last Survey, No. 29619 Port of Lon. Classed 10 AI.
11, 68.

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>Good and</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers	} <u>where</u>	Keelsons	} <u>where</u>	Anchors No. of	} <u>complete</u>
Sheerstrakes		Clamps and Shelves		Cables	
Topsides	} <u>seen.</u>	Ceiling	} <u>seen.</u>	Hawsers and Warps	} <u>where seen.</u>
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>4. 11.</u> When put on <u>168.</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.
Yellow metal patched.
Is now in good and efficient condition, and fit
in my opinion to remain as classed - 10 AI.

Committee's Minute 1st November 1870

Character assigned 10 AI

Certificate (if required).