

# ANNUAL SURVEYS.

31221

Recd. 9.11.70

No. 215 Survey held at London Date 8<sup>th</sup> Nov 1870  
 on the bark "Fontabelle" Master E. Nixon  
 Tonnage 361 Built at Bristol When built 1835  
 By whom built --- Owners Sawson & Co  
 Port belonging to London Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock Walters dry dock and afloat

Last Survey, No. 3015 Port of Bres. Classed B.A.1  
 (cont. 68 - 9 Nov 9.68)

The present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>14<sup>th</sup> Nov</u> When put on <u>1868</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where examined  
Patched Yellow Metal Sheathing  
is now in good and efficient condition, and in  
my opinion eligible to remain as classed.  
 Committee's Minute 11<sup>th</sup> November 1870  
 Character assigned Cont 9 1 11/11  
 Certificate (if required)

No. 132 Survey held at London Date 4<sup>th</sup> Nov 1870  
 on the Ship "Belles Gile" Master A. Locke  
 Tonnage 812 Built at Workington When built 1863 - 7 mo  
 By whom built Self Owners Rushby & Co  
 Port belonging to Workington Destined Voyage Hong Kong  
 If Surveyed Afloat or in Dry Dock Limekiln Dry Dock and afloat

Last Survey, No. 3047 Port of Lon. Classed 14 A1  
 (pt Iron Beams 11.69)

The present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>14<sup>th</sup> Nov</u> When put on <u>1869</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where examined  
Patched Yellow Metal Sheathing  
is now in good and efficient condition, and in my  
opinion eligible to remain as classed.  
 Committee's Minute 11<sup>th</sup> November 1870  
 Character assigned 14 A1  
 Certificate (if required).