

31226

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 463 No. 30288 Survey held at London Date, first Survey 1865 Last Survey 4 Nov 70
on the Ship 'Cingala' Master E. Neilson
Tonnage 799 built at Workington When built 1865-1 mo
By whom built Canport Owners W. Nicol
Port belonging to London Destined Voyage Hong Kong
If Surveyed Afloat or in Dry Dock Rately Dry Dock and Afloat.

Last Survey, No. 30288 Port Lon. Classed 14 A1
cf 8.69

REPAIRS, &c.

Stripped Yellow Metal Sheathing, caulked from keel to gunwale, and resheathed bottom with Yellow Metal on felt.

Cross-jack yard, main topsail-yard and Main-topmast herr of Pine.

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>—</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>—</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>—</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>Examined aloft.</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>2 Good</u>
Topsides	Ceiling	Cables	<u>and</u>
Wales	Rudder	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>At the</u> When put on <u>new</u>	Standing & Running Rigging	<u>Good</u>
Engine Room Skylights	Caulking of <u>3 good where</u>	Cargo and Main Hatchways	<u>good</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>3 tested</u>	Hatches	<u>good</u>
General Observations and Opinion,	Scuppers <u>good</u>		

Is now in good and efficient condition and in our opinion eligible to remain as classed.

The Amount of Entry Fee.....£ — : — : is received by me,

Special.....4 : 4 :

Certificate (if required).....

Committee's Minute 15th November 70 18

Character assigned 14 A1

W. H. Turner
W. H. Turner