

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 190 No. 30581 Survey held at London Date, first Survey 2nd Nov^r Last Survey 14 Nov^r 1870
 on the Ship "Profussilite" Master A. C. Rae
 Tonnage 1009 built at Glasgow When built 1864-9 mo
 By whom built Stephen Owners Allan & Sons
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Amelika Dry Dock
 Last Survey, No. 30581 Port Lon. Classed 17 A1
 REPAIRS, &c. 15.5.69, 12.69

Stripped Yellow Metal Sheathing, caulked from keel to metal line, and resheathed bottom with Yellow Metal on tub.

Present Condition of the

| | | |
|-----------------------------------|---|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places | Condition, how ascertained |
| Planksheers | Keelsons | Sails |
| Sheerstrakes | Clamps and Shelves | Anchors No. of |
| Topsides | Ceiling | Cables |
| Wales | Rudder | Hawsters and Warps |
| Plank (Bottom) and Counter | Copper <u>4th</u> When put on <u>Nov^r</u> | Standing & Running Rigging |
| Engine Room Skylights | Caulking of <u>3rd bottom</u> | |
| Coal Bunker, Openings, Lids, &c. | Bottom, Deck, & Waterways <u>3rd bottom</u> | |
| General Observations and Opinion, | Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u> | |

Is now in good and efficient condition, and in my opinion eligible to remain as classed.

The Amount of Entry Fee.....£ - : - : is received by me,

Special.....1 : 1 : *A.C.R.*

Certificate (if required) : 5 : *15.11.70*

Committee's Minute *15th November 1870*

Character assigned *17 A1*
recorded
M.A.