

# ANNUAL SURVEYS.

31257

No. 368 Survey held at London Date 5<sup>th</sup> Novemb<sup>r</sup> 1870  
 on the Ship "John Emperley" Master Sucker  
 Tonnage 976 Built at Lusserland When built 1836  
 By whom built Hall Owners Emperley  
 Port belonging to London Destined Voyage Manilla via Cardiff  
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 30357 Port of Lore

Classed B. A. 1  
Cont<sup>d</sup> 69-4 Yrs. 69

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper At the When put on 1869

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Deck pintle and brace repaired, patched Yellow Metal sheathing  
 Is now in good and efficient condition, and in  
 my opinion eligible to remain as classed.

Committee's Minute 6<sup>th</sup> December 1870

Character assigned

Cont<sup>d</sup> 4 1/2 1 1/2