

REPORT of SURVEY for REPAIRS.

31302

No. in Reg. Book. 190 No. 190 Survey held at London Date, first Survey 12th 13th Last Survey 14th 22 18th
 on the Barque Lionie Master John Lelcan
 Tonnage 289 built at Bristol When built 1857
 By whom built — Owners J. Wilson
 Port belonging to London Destined Voyage Antwerp
 If Surveyed Afloat or in Dry Dock London Docks afloat.

Last Survey, No. — Port — Classed 13. A. 1.

REPAIRS, &c.

Examined Ceiling in the lower Hold in Midships
 cut out defects, and inserted graven pieces (two each side)
 renewed, or made good the latches where required. also the
 main rail at the junction of the Poop, each side.
 gave her a new taffrail, and completed the Survey for
 the Clap. —

Present Condition of the

Decks	good	Treenails	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	"
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	"
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper <u>4 Months</u> When put on <u>1869</u>	good	Standing & Running Rigging	"
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Caulking of	good		
		Bottom, Deck, & Waterways			
		Scuppers	good	Cargo and Main Hatchways	good
				Hatches	good

General Observations and Opinion,

Repairs having been now completed as recommended
 we are of opinion, she is eligible to be continued G.A. 1.
 from 1870.

Samuel Presious
 W. W. W. W. W.

The Amount of Entry Fee.....£ : : is received by me,

Special..... 1 : 1 : :

Certificate (if required) : 5 : :

Committee's Minute 23rd December 1874

Character assigned Cont'd for 9 years

record repair = part 9 years



© 2021

Lloyd's Register
 Foundation

LONG56 - 0184