

# ANNUAL SURVEYS.

31434

No. 335 Survey held at London Date 13<sup>th</sup> Jan'y Feb'y 20<sup>th</sup> 1871  
 on the Ship Turkish Empire Master J. Barclay  
 Tonnage 1502 Built at Hartlepool When built 1856  
 By whom built — Owners G. Duncan  
 Port belonging to London Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Thames dry dock & London Docks

Rev 23/2/71

Last Survey, No. 30737 Port of Lon. Classed Res<sup>d</sup>/66, 10<sup>th</sup> A. I.  
 dia. doubled 2-70

The present Condition of the

Decks	good	Treenails	where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors	No. of 3 & 1 S. 2 K
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	efficient	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	Feet & 1/2 m When put on 1870	"		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Repaired the yellow metal. — She is in good condition and I am of opinion. — She is entitled to remain as Clap'd

Res<sup>d</sup> 10. A. I.

Samuel Presions

Committee's Minute 24<sup>th</sup> February 1871

Character assigned Res<sup>d</sup> 10. A. I.

Certificate (if required)

No. 543 Survey held at London Date 16 Jan'y Feb'y 20<sup>th</sup> 1871  
 on the Barque Clara Master Joseph Nelson  
 Tonnage 623 Built at Sunderland When built 1853  
 By whom built — Owners Stuart & Co.  
 Port belonging to Liverpool Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Wigram's dry dock & S.W. India docks.

Last Survey, No. 30531 Port of Lon. Classed Res<sup>d</sup>/67, 7. A. I.  
 11. 69

The present Condition of the

Decks	good	Treenails	where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors	No. of 3 & 1 S. 2 K
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	efficient	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	pt E & D 1/2 m When put on 67 & 69	"		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

She is in good condition and I am of opinion She sighted the yellow metal and patched it. — is entitled to remain as Clap'd

Res<sup>d</sup>/67, 7. A. I.

Samuel Presions

Committee's Minute 24<sup>th</sup> February 1871

Character assigned Res<sup>d</sup> 7 A. I.

Certificate (if required)

LON656 - 0259



Handwritten text at the top of the page, possibly a title or header, including the word "Clear".



© 2021

Lloyd's Register  
Foundation