

REPORT of SURVEY for REPAIRS.

314609
[Signature]

No. in Reg. Book. 145 No. 30709 Survey held at London Date, first Survey Feb 9th Last Survey Feb 28th 1871
 on the S. Barnagheen Master Colville
 Tonnage 825 built at Aberdeen When built 1867
 By whom built Humphreys Owners Common & Co
 Port belonging to Aberdeen Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock King + Queen dry dock + London Dock
 st Survey, No. 30709 Port Lon. Classed G.A. 1

Recd 4/2/71

PAIRS, &c.

Yellow metal stripped off recaulted from keel to metal lin and the yellow metal removed on felt.

| Condition of the | | Treenails | | Windlass and Capstan | |
|-----------------------------------|--------------|--|--------------|----------------------------|--------------|
| Waterways | | Breasthooks and Stemson | | Pumps | |
| Beams | | Transoms, Pointers, and Crutches | | Boats | |
| Deck Beams & Fastenings | } Good | Timbers of the Frame at the openings | } Good | Masts, Yards, &c. | } Good & |
| Deck Beams & Fastenings | | Ditto Ditto at other places | | Keelsons | |
| Sheers | } where seen | Clamps and Shelves | } where seen | Sails | } sufficient |
| Strakes | | Ceiling | | Rudder | |
| Sides | | Copper <u>F + J M</u> When put on <u>new</u> | | Cables | |
| Keels | | Caulking of | | Hawsers and Warps | |
| Keel (Bottom) and Counter | | Bottom, Deck, & Waterways | good | Standing & Running Rigging | |
| Engine Room Skylights | | Coal Bunkers, Openings, Lids, &c. | | Cargo and Main Hatchways | good |
| General Observations and Opinion, | | Scuppers | | Hatches | good |

This vessel is eligible in my opinion to remain as classed G.A. 1

[Signature]
 J. H. Wain

Amount of Entry Fee..... £ : : is received by me,
 Special..... 1 : 1 :
 Certificate (if required) : 5 :

's Minute 10th March 18 71

assigned G.A. 1 record J.M.



© 2021
 Lloyd's Register
 Foundation

LON656-0273