

ANNUAL SURVEYS.

31494

No. 124 on the Ship "The Goolwa" Survey held at London Date 8th Feb^y - 7th March 1871
 Master A. Johnston
 Tonnage 417 Built at Aberdeen When built 1864
 By whom built Hall Owners Anderson & Co.
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock In Dry Dock.

[Signature]

Recd. 23/3/71

Last Survey, No. 30904 Port of Am. Classed 15 A 1.
 4, 70.

The present Condition of the

Decks	Treenails C. H.	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper H. L. M. When put on 1869.	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.
 Yellow metal patched, and coated with Peacock's Composition.
 Is now in good and efficient condition, and fit in my opinion
 to remain classed 15 A 1.
 J. H. Eastlake.

Committee's Minute 24th March 1871

Character assigned 15 A 1

[Signature]

Certificate (if required)

No. 42 on the Ship "Sir Robert Sale" Survey held at London Date 17th March 1871.
 Master S. Sales
 Tonnage 741 Built at Malmeir When built 1843
 By whom built Owners Leigh & Co.
 Port belonging to London Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock In Dry Dock and Afloat

[Signature]

Last Survey, No. 30623 Port of Lon. Classed 12
 10 A 4 - A 11 Red
 5564-84m. 1.70

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper Yellow Metal When put on 1870	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.
 Planks hooding out, patched Yellow Metal Sheathing Main
 topmast part of Pine. Is now in good and efficient condition
 fit for the safe conveyance of dry and perishable cargoes to and
 from all parts of the world and in
 my opinion eligible to remain as
 classed. J. H. Eastlake.

Committee's Minute 24th March 1871

Character assigned 15 A 1

[Signature]

Certificate (if required).

LON656-0296