

31525

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 39 No. S. Tamesa Survey held at London Date, first Survey March 9th Last Survey April 11th 18 71
 on the S. Tamesa Master W. O. Phillips
 Tonnage 713 built at Sunderland When built 1869 - 9 mo
 By whom built Doxford Owners Jolls + Co
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Princes dry dock + W. S. Dock
 Last Survey, No. 9704 Port Std. Classed 16 A 1
 REPAIRS, &c. 10. 89

The bottom sighted & yellow metal repaired

Present Condition of the

Decks	} <i>Good</i>	Treenails	} <i>Good</i>	Windlass and Capstan	} <i>Sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>F. J. M.</u> When put on <u>1869</u>		Standing & Running Rigging	
Engine Room Skylights		Caulking of			
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways <i>good</i>			
Scuppers				Cargo and Main Hatchways	
Hatches				<i>good</i>	

General Observations and Opinion,

This vessel is eligible in my opinion to remain as classed 16 A 1

The Amount of Entry Fee.....£ : : is received by me,

Special..... £ : : -

Certificate (if required) : :

Committee's Minute 14th April 18 71

Character assigned 16 A 1

Thos. W. Wain



© 2021 Lloyd's Register Foundation LON 656-0318