

REPORT of SURVEY for REPAIRS.

31697

No. in Reg. Book. **309** No. **13** Survey held at **London** Date, first Survey **May 24th** Last Survey **June 10th 18**
 on the **"Alice"** Master **Pounder**
 Tonnage **474** built at **Sunderland** When built **1852**
 By whom built _____ Owners **Brodie &**
 Port belonging to **London** Destined Voyage **Penang**
 If Surveyed Afloat or in Dry Dock **Princes dry dock & London Dock**
 Last Survey, No. **30214** Port **Lon.** Classed **9 A 1**
 Cont **66 - 6 6.69**

REPAIRS, &c.

Yellow metal sheathing stripped off, recaulked from keel to plank sheers & the yellow metal renewed on felt - Main mast renewed with Pitch Pine -

Continued in July 1867 the owner declined the half time until her return from the present voyage - Cables ranged (270 fms. good)

Present Condition of the

Decks	Good when seen	Treenails	Good when seen	Windlass and Capstan	Good & sufficient
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Plank sheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables 270 fms.	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper T & Y M When put on now		Standing & Running Rigging	
Engine Room Skylights	Caulking of	Cargo and Main Hatchways	Hatches good		
General Observations and Opinion,	Bottom, Deck, & Waterways Good	Scuppers			

This vessel is eligible in my opinion to remain as classed **MS**

The Amount of Entry Fee.....£ : : is received by me, **Thos. W. Wawn**

Special..... 1 : 1 : **WMC 28/6/71**

Certificate (if required) : 5 :

Committee's Minute **30th June** 18 **71**

Character assigned **Cont'd B 12 1**
renewed WMC



© 2021

Lloyd's Register Foundation

LON656-0434