

REPORT of SURVEY for REPAIRS.

31893

No. in Reg. Book. *63* No. *31245* Survey held at *London* Date, first Survey *5th Feb^r* Last Survey *Feb^r 19th 1871*
 on the Ship *Zenobia* Master *J. Hutchings*
 Tonnage *1145* built at *Bombay* When built *1851*
 By whom built *-* Owners *J. Willis*
 Port belonging to *London* Destined Voyage *-*
 If Surveyed Afloat or in Dry Dock *Nelson dry dock &*
 Last Survey, No. *31245* Port *London* Classed *17. A. 1. 10, 70*
Com^d 1/68. 11. A. 1.

REPAIRS, &c.

*Stripped off the whole of the Yellow Metal Sheathing,
 Made good the Caulking of the butts and seams from
 the keel to gunwale. Resheathed with Yellow Metal
 on felts. -*

Present Condition of the

Decks	<i>good</i>	Treenails	<i>where seen</i>	<i>good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stenson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	"
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of <i>3 B, 1 S, 2 R</i>	"
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder <i>efficient</i>	"	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	<i>Copper felt with</i> When put on <i>now</i>	"	"	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of <i>good when tested</i>	"	"		
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	"	"		
Scuppers	<i>good</i>	Cargo and Main Hatchways	<i>good</i>	Hatches	<i>good</i>	

General Observations and Opinion,

*She is as far as seen in good condition
 and is in my opinion entitled to remain as class'd
 Com^d 1/68. 11. A. 1.
 Samuel Presnall*

The Amount of Entry Fee.....£ - : - : is received by me,

Special..... 2 : 2 :

Certificate (if required).....

Committee's Minute *26th September 1871*

Character assigned *Com^d 11th*



© 2021

Lloyd's Register
Foundation

LOV654-0085

