

REPORT of SURVEY for REPAIRS.

31938

No. in Reg. Book. 129 No. 13th Survey held at London Date, first Survey Oct 9th 1871 Last Survey Oct 9th 1871
 on the "Georgetown" Master A. Collard
 Tonnage 414 built at Sunderland When built 1858
 By whom built — Owners Colonial Co. Ltd.
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock London Dock afloat
 Last Survey, No. 31099 Port Lon. Classed Cont 7 A. 1
 REPAIRS, &c. 9.7°

Main piece of Rudder removed with C. Oak.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>where</u>	Condition, how ascertained <u>and</u>
Planksheers <u>where</u>	Keelsons <u>"</u>	Sails <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B. 1 L. 2 R.</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Wales <u>"</u>	Rudder <u>sun</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>sun</u>	Copper <u>47. m</u> When put on <u>1870</u>	Standing & Running Rigging <u>Sufficient</u>
Engine Room Skylights <u>—</u>	Caulking of <u>—</u>	Hatches <u>Good</u>
General Observations and Opinion,	Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
	Coat Bunker, Openings, Lids, &c. <u>—</u>	Scuppers <u>Good</u>

This vessel is where seen in good condition, and in my opinion eligible to remain as classed.

The Amount of Entry Fee.....£ — : — } is received by me,
 " Special..... 1 : 1 } J. Lawrence
 Certificate (if required) : 5 : } 13.10.71.

Committee's Minute 17th October 1871
 Character assigned Cont 7 A. 1



© 2021

Lloyd's Register Foundation

LOW 657-0119