

REPORT of SURVEY for REPAIRS.

32071

No. in **No.** Survey held at London Date, first Survey 15 Dec 71 Last Survey 12 Jan 72 1872
 on the Ship 'Caspatrik' Master A. Elmlic
 Tonnage 1200 built at Moulmein When built 1856
 By whom built _____ Owners J. Fleming
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Port Green's dry dock and afloat
 Last Survey, No. 31250 Port Lon. Classed B.A.1.
 REPAIRS, &c. Cont^d 14 Yrs.
11.70

Stripped Yellow Metal sheathing, caulked from keel to upper edge of wales; and resheathed bottom with Yellow Metal on Self.

Present Condition of the Decks _____ Waterways _____ _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Tank (Bottom) and Counter _____ Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____	Treenails _____ Breasthooks and Stemson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame at the openings _____ Ditto Ditto at other places _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper _____ Caulking of _____ Bottom, Deck, & Waterways _____	Windlass and Capstan <u>Good</u> Pumps _____ Boats _____ Masts, Yards, &c. _____ Condition, how ascertained <u>seen from below</u> Sails _____ Anchors No. of _____ Cables _____ Hawser and Warps _____ Standing & Running Rigging _____ _____
--	--	--

Work done here

Wales have been

Is now in good, and efficient condition, and in my opinion eligible to remain as classed.

The Amount of Entry Fee.....£ _____ } is received by me,
 Special..... 1 : 1 : }
 Certificate (if required) _____ }
W. Turner's

Committee's Minute 23rd January 1872
 Character assigned Cont^d 14 Yrs.

© 2021
 Lloyd's Register
 Foundation

 LRG 0219