

ANNUAL SURVEYS.

32215

No. 278 Survey held at London Date 2nd March 18th 1872
on the Barque Robert Morrison Master Charles Horton
Tonnage 855 Built at Sunderland When built 1853
By whom built _____ Owners Wilson & Co
Port belonging to London Destined Voyage Swan River
If Surveyed Afloat or in Dry Dock Horse Ferry dry dock & London Docks

Last Survey, No. 30108 Port of Lon. Classed Cont^d 166. G. A. I.

The present Condition of the

Decks	<u>good</u>	Treenails	<u>where seen</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	"
Planksheers	"	Keelsons		"	Anchors, No. of	<u>3 B. 13. 2 K</u>
Sheerstrakes	"	Clamps and Shelves		"	Cables	"
Topsides	"	Ceiling		"	Hawsers and Warps	"
Wales	"	Rudder	<u>efficient</u>	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	<u>Felt & ymsl</u> When put on <u>1871</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Survey'd in ballast.

Repaired the Yellow metal sheathing

I am of opinion she is entitled to remain as clasp'd

Committee's Minute 26th March 18th 72

Character assigned

Samuel Presions deferred

Certificate (if required).

No. 87 Survey held at London Date 11th March 18th 1872
on the Ship Daylight Master Hy Pearce
Tonnage 629 Built at Sunderland When built 1857
By whom built _____ Owners Wilson & Co
Port belonging to London Destined Voyage Cardiff
If Surveyed Afloat or in Dry Dock Princes dry dock

Last Survey, No. 31365 Port of Lon. Classed Cont^d 170. G. A. I.

The present Condition of the

Decks	<u>good</u>	Treenails	<u>where seen</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	"
Planksheers	"	Keelsons		"	Anchors, No. of	<u>3 B. 13. 2 K</u>
Sheerstrakes	"	Clamps and Shelves		"	Cables	"
Topsides	"	Ceiling		"	Hawsers and Warps	"
Wales	"	Rudder	<u>efficient</u>	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	<u>Felt & ymsl</u> When put on <u>1870</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Survey'd in Ballast

Doubled a large portion of the Yellow metal sheathing.

I am of opinion she is entitled to remain as clasp'd

Committee's Minute 26th March 18th 72

Character assigned

Cont^d G. A. I.

Samuel Presions

Certificate (if required).

Robert Morrison
Daylight



© 2021

Lloyd's Register
Foundation