

# ANNUAL SURVEYS.

32218

No. 9

Survey held at

London

Date

13<sup>th</sup> March

1872

on the

Ship "Maid of Judah"

Master

D. Bain

Tonnage

756

Built at

Aberdeen

When built

1853

By whom built

W. Wood

Owners

Shompson

Port belonging to

Aberdeen

Destined Voyage

Australia

If Surveyed Afloat or in Dry Dock

Canal dry dock

Rev. 25/3/72

Last Survey, No.

31027

Port of

Lon.

Classed

A in Red

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

1870

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Lullon Metal Sheathing. Is now in good and efficient condition, fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world and in my opinion eligible to remain as classed.

Committee's Minute

26<sup>th</sup> March 1872

Character assigned

A in Red

J. P. M. H. Turner

Certificate (if required).

No. 129

Survey held at

London

Date

15<sup>th</sup> March 1872

on the

Ship "The Lord Garden"

Master

John Smith

Tonnage

1237

Built at

Sunderland

When built

1862. 5 mo

By whom built

Pile

Owners

Robt. Green

Port belonging to

London

Destined Voyage

Melbourne

If Surveyed Afloat or in Dry Dock

Robt. Green's dry dock

Last Survey, No.

31681

Port of

Lon.

Classed

13 A 1

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

1871

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Lullon Metal Sheathing. Is now in good and efficient condition, and in my opinion eligible to remain as classed.

Committee's Minute

26<sup>th</sup> March 1872

Character assigned

13 A 1

J. P. M. H. Turner

Certificate (if required).