

REPORT of SURVEY for REPAIRS.

32266

No. in Reg. Book. 362 No. 1292 Survey held at London Date, first Survey Sept Last Survey 15th Apr 1872
 on the Ship "Shannon" Master V. R. C. Staepole
 Tonnage 1292 built at London When built 1862 - 5 mo
 By whom built Green Owners Robt Green
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Robt Green's dry dock
 Last Survey, No. 31801 Port Lon. Classed 13A1. 2P. 1
 REPAIRS, &c. cf.

Stripped Yellow Metal Sheathing, hung in shores caulked from keel to gunwale, and resheathed bottom with Yellow Metal on felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>4</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>4</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>4</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>Seen from the deck</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>Good</u>
Topsides	Ceiling	Cables	<u>and</u>
Wales	Rudder	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>At the</u> When put on <u>1872</u>	Standing & Running Rigging	<u>Good</u>
Engine Room Skylights	Caulking of <u>3 good where tested.</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Hatches	<u>Good</u>
General Observations and Opinion,	Scuppers <u>Good</u>		

Is now in good and efficient condition, and in my opinion eligible to remain as classed.

W. H. Turner

The Amount of Entry Fee.....£ — : — : is received by me,
 Special..... / : / : — A. G. D.
 Certificate (if required) : 5 : 5 19.4.72

Committee's Minute 28th April 1872

Character assigned

13A1 record 9M

J. P. W.



© 2021

Lloyd's Register Foundation