

# REPORT of SURVEY for REPAIRS.

32356

No. in Reg. Book. 812 No. 1 Survey held at London Date, first Survey 17<sup>th</sup> May Last Survey 27<sup>th</sup> May 1874  
 on the Ship "Asterope" Master Homer  
 Tonnage 651 built at Aberdeen When built 1859  
 By whom built A. Hall & Co Owners Parker & Co  
 Port belonging to London Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock Both - Green's dry dock  
 Last Survey, No. 31023 Port Lon. Classed B.A.

REPAIRS, &c.

Half Line Survey held at London 17<sup>th</sup> May  
in April 1874. vide Report No 27440

Caulked from Metal line over all, and patched  
Yellow Metal Sheathing.

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>Good</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>Seen from the deck</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>Good</u>
Topsides	Ceiling	Cables	<u>and</u>
Wales	Rudder	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>As then</u> When put on <u>1870</u>	Standing & Running Rigging	<u>Good</u>
Engine Room Skylights	Caulking of <u>3</u> <u>good where</u>	Cargo and Main Hatchways	<u>good</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>3</u> <u>Examine</u>	Hatches	<u>good</u>
General Observations and Opinion,	Scuppers <u>good</u>		

Is now in good and efficient condition, and  
in my opinion eligible to remain as classed.

M. Turner

The Amount of Entry Fee.....£ - : - : is received by me,

Special..... / : / :

Certificate (if required) : 5 :

Committee's Minute 4<sup>th</sup> June 1874

Character assigned B.A.

M. Turner



© 2021

Lloyd's Register Foundation