

REPORT of SURVEY for REPAIRS.

32527

No. in Reg. Book. 614 No. 3015 Survey held at London Date, first Survey Jan 14th Last Survey July 13th 1872
 on the B^d "Mayola" Master Masson
 Tonnage 400 built at Belfast When built 1856
 By whom built _____ Owners Hunter
 Port belonging to Glasgow Destined Voyage Rangoon
 If Surveyed Afloat or in Dry Dock Ratchiff Dry Dock
 Last Survey, No. 3015 Port Glas. Classed S.A.S. Cond 69-9A.S.
9.69.

No. 26774

REPAIRS, &c.

Stripped off all the yellow metal sheathing caulked from rail to gunwale re-shathed with yellow metal on felt.

Present Condition of the

Decks	<u>Good</u>	Treenails <u>Where seen good</u>		<u>Good</u>
Waterways	"	Breasthooks and Stemson		
Comings	"	Transoms, Pointers, and Crutches		
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		
Planksheers	"	Keelsons		
Sheerstrakes	"	Clamps and Shelves		
Topsides	"	Ceiling		
Wales	"	Rudder		
Plank (Bottom) and Counter	"	Copper <u>F.Y.M.</u> When put on <u>now</u>		
Engine Room Skylights		Caulking of		
		Bottom, Deck, & Waterways	<u>Good</u>	
		Coal Bunker, Openings, Lids, &c.	<u>Good</u>	
		Scuppers	<u>Good</u>	
		Cargo and Main Hatchways	<u>Good</u>	
		Hatches	<u>Good</u>	
		Windlass and Capstan		<u>Good</u>
		Pumps		
		Boats		
		Masts, Yards, &c.		
		Condition, how ascertained		
		Sails		<u>And</u>
		Anchors No. of		
		Cables		
		Hawsers and Warps		
		Standing & Running Rigging	<u>Sufficient</u>	

General Observations and Opinion,

This vessel is now in good condition and in my opinion eligible to remain as classed.

J. Lawrence

The Amount of Entry Fee.....£ : : is received by me,
 Special..... / : / : 076. 21.1
23/8/72
 Certificate (if required) : : :

Committee's Minute 24th August 1872
 Character assigned Cond 9

recd G. M.
 WMS



© 2021
 Lloyd's Register
 Foundation
 LON 657-0508