

# REPORT of SURVEY for REPAIRS.

32529

No. in Reg. Book. 315 No. 1 Survey held at London Date, first Survey 2<sup>nd</sup> Apr 6 Last Survey 5<sup>th</sup> Apr 18  
 on the Ship "Loxford" Master Hansford  
 Tonnage 270 built at Shields When built 1856  
 By whom built Smith Owners J. Southern  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Pott. Green's dry dock  
 Last Survey, No. 31614 Port Lon. Classed 6 A 1

REPAIRS, &c.

Port 66-7 Years  
(HT. Lond. 69) cf 5.71

*Stripped Yellow Metal Sheathing caulked from keel to gunwale, and resheathed bottom with Yellow Metal on Selt.*

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>"</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>"</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>seen from the deck</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>and</u>
Topsides	Ceiling	Cables	<u>sufficient</u>
Wales	Rudder	Hawsers and Warps	<u>"</u>
Plank (Bottom) and Counter	Copper <u>to 1/2 in</u> When put on <u>1872</u>	Standing & Running Rigging	<u>good</u>
Engine Room Skylights	Caulking of <u>3 good where</u>		
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>3 tested</u>		
Scuppers	<u>good</u>	Cargo and Main Hatchways	<u>good</u>
Hatches	<u>good</u>		

General Observations and Opinion,

*I now in good, and efficient condition, and in my opinion eligible to remain as classed.*

*J. H. Turner*

The Amount of Entry Fee.....£ — : — : is received by me,

Special..... / : / :

Certificate (if required)..... : : :

Committee's Minute 30<sup>th</sup> August 1872

Character assigned Port 7

*revised J. M.*

*W. M.*