

32564

Composite
REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *39* No. *1* Survey held at *London* Date, first Survey *7th Dec* Last Survey *Dec 31st 18*
on the *S. + Pamela* Master *Jones - E. G.*
Tonnage *713* built at *Sunderland* When built *1869* g. ms.
By whom built _____ Owners *Jolly & Co*
Port belonging to *London* Destined Voyage *Adelaide*
If Surveyed Afloat or in Dry Dock *Purves dry dock & London Dock*
Last Survey, No. *31525* Port *London* Classed *16 A B*

REPAIRS, &c.

Yellow Metal stripped off; recaulked from steel to line of Metal, and the yellow Metal renewed on Sill.

Present Condition of the

| | | | | | |
|-------------------------------|----------------------------------|--|--------------------------|----------------------------|-------------------|
| Decks | <i>Good where seen</i> | Treenails | <i>Good where seen</i> | Windlass and Capstan | <i>Sufficient</i> |
| Waterways | | Breasthooks and Stemson | | Pumps | |
| Comings | | Transoms, Pointers, and Crutches | | Boats | |
| Upper Deck Beams & Fastenings | | Timbers of the Frame at the openings | | Masts, Yards, &c. | |
| Lower Deck Beams & Fastenings | | Ditto Ditto at other places | | Condition, how ascertained | |
| Planksheers | | Keelsons | | Sails | |
| Sheerstrakes | | Clamps and Shelves | | Anchors No. of | |
| Topsides | | Ceiling | | Cables | |
| Wales | | Rudder | | Hawsers and Warps | |
| Plank (Bottom) and Counter | | Copper <i>L. Y. M.</i> When put on <i>none</i> | | Standing & Running Rigging | |
| Engine Room Skylights | Coal Bunker, Openings, Lids, &c. | Scuppers | Cargo and Main Hatchways | Hatches <i>good</i> | |

General Observations and Opinion,

This vessel appears eligible in my opinion to remain as classed A B

The Amount of Entry Fee.....£ - : : }

is received by me,

Thos. M. Dawn

Special..... 1 : 1 : }

Certificate (if required) : 5 : }

Committee's Minute

7th January 18 93

Character assigned

16 A B

*received by me
J. J. M.*



© 2021

Lloyd's Register
Foundation

LON 658-0133