

ANNUAL SURVEYS.

32849

No. 159 Survey held at London Date 15th Jan'y 23rd 1872
 on the Barque Benjamin Buck Green Master R. Bowman
 Tonnage 544 Built at Cowes When built 1846
 By whom built 528 Owners Blyths & Co
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Regent dry dock

Recd. 1.10.72
Ent'd

Last Survey, No. 32216 Port of London Classed S.S./64. S.A. 1.
 The present Condition of the
 Decks good Treenails good where seen Windlass and Capstan in good order
 Waterways " Breasthooks and Stemson good Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Masts, Yards, &c. new main topmast
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
 Planksheers " Keelsons " Anchors, No. of 3 B. 1 S. 2 H
 Sheerstrakes " Clamps and Shelves " Cables "
 Topsides " Ceiling " Hawseers and Warps "
 Wales " Rudder efficiently Standing and Running Rigging "
 Plank (Bottom) and Counter " Copper When put on
 General Observations and Opinion, Sighted with Port side up? below bulwark. Caulking of Bottom, Deck, and Waterways good
Survey'd with part cargo on board.
She is in good condition and in my opinion is entitled to remain as class'd S.A. 1. in red.
 Committee's Minute 4th February 1873 Samuel Piesius
 Character assigned A in red DPW
 Certificate (if required).

No. 922 Survey held at London Date 13th Jan'y 23rd 1873
 on the Ship Cuyuni Master Rt^l Playe
 Tonnage 491 Built at Port Glasgow When built 1856
 By whom built " Owners Ewing & Co
 Port belonging to Glasgow Destined Voyage Clyde
 If Surveyed Afloat or in Dry Dock Union dry dock

Recd. 1.10.73

Last Survey, No. 5911 Port of Glasgow Classed Cont^d/66. S.A. 1.
 The present Condition of the
 Decks good Treenails good where seen Windlass and Capstan in good order
 Waterways " Breasthooks and Stemson good Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Masts, Yards, &c. "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
 Planksheers " Keelsons " Anchors, No. of 3 B. 1 S. 2 H
 Sheerstrakes " Clamps and Shelves " Cables "
 Topsides " Ceiling " Hawseers and Warps "
 Wales " Rudder efficiently Standing and Running Rigging "
 Plank (Bottom) and Counter " Copper When put on
 General Observations and Opinion, Sighted the 9. Metal & repaired in the new bulwark station & flathead She is now in good condition and entitled to remain as class'd cont^d/66. S.A. 1. Caulking of Bottom, Deck, and Waterways good
Survey'd with part cargo on board.
 Committee's Minute 4th February 1873. Samuel Piesius
 Character assigned Cont^d 7A DPW
 Certificate (if required).

Lloyd's Register Foundation

Benjamin Franklin 1750



© 2021

Lloyd's Register
Foundation