

REPORT of SURVEY for REPAIRS.

32894

No. in Reg. Book. **No.** Survey held at London Date, first Survey 17 Jan Last Survey 21 Feby 1873.
 on the Ship "Shannon" Master V. C. Stactpole
 Tonnage 1292 built at London When built 1862 5mo
 By whom built Green Owners R & M Green
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock R & M Green's Dry Dock & E. I. O.
 Last Survey, No. 32966 Port London Classed 13 A 1.

REPAIRS, &c. Now done on account of Damage "H.T. '71" - 4/72 -
 For Particulars see Special Reports. 2 Stanchions, 2 lengths of Rail on Port deck renewed. Main Rail forming Port Sheer in waist on Starboard side, wash boards, Port Rails - Skylight frames and fittings renewed and repaired. Boats, and other details of Equipments made good, and efficient; Vessel placed on blocks in graving dock. Yell. sheathing repaired, and coated with Peacock's Paint - caulked over all from metal line to metal line.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Y.M.F.</u> When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations and Opinion, Vessel appears in good and efficient condition, and eligible to remain as classed "A 1".
Henry J. Syrett

The Amount of Entry Fee.....£ : : is received by me,
 Special..... : :
 Certificate (if required) : :

Committee's Minute 25th Feby 1873
 Character assigned 13 A 1
Special Damage £5. 5. 0
J.P.W.