

ANNUAL SURVEYS.

33097
Recd 10.6.73

186 No. 186 Survey held at London Date 2nd May 1873
on the Comp. S. Electra Master Sellers
Tonnage 668 Built at Aberdeen When built 1866 - 5mo
By whom built Hall Owners Parker & Co.
Port belonging to London Destined Voyage Wellington
If Surveyed Afloat or in Dry Dock Princes Dry Dock & East India Dock

Last Survey, No. 31727 Port of London Classed 1st A 1
The present Condition of the
Decks Good Treenails Good Windlass and Capstan Good
Waterways do Breasthooks and Stemson do Pumps do
Comings do Transoms, Pointers, and Crutches do Boats Four
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Masts, Yards, &c. Good and Sufficient
Lower Deck Beams & Fastenings do Ditto ditto at other places do Sails do
Planksheers do Keelsons do Anchors, No. of 30. 14. 24
Sheerstrakes do Clamps and Shelves do Cables Good
Topsides do Ceiling do Hawser and Warps and
Wales do Rudder do Standing and Running Rigging Sufficient
Plank (Bottom) and Counter do Copper Y.M. When put on 1871
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good
Now done. Bottom sighted and yellow metal patched. She is in good condition, and is in my opinion eligible to remain as classed.
Committee's Minute 13th June. 1873
Character assigned 17A1 TDW James M. Neil
Certificate (if required).

50 No. 50 Survey held at London Date 3rd May 1873
on the B. Ensign Master Tomning
Tonnage 315 Built at Shoreham When built 1870 - buw
By whom built May Owners Gates & Co.
Port belonging to Shoreham Destined Voyage
If Surveyed Afloat or in Dry Dock Duke Shore Dry Dock & Afloat

Last Survey, No. 1437 Port of Southampton Classed 10A1
The present Condition of the
Decks Good Treenails Good Windlass and Capstan Good
Waterways do Breasthooks and Stemson do Pumps do
Comings do Transoms, Pointers, and Crutches do Boats do
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Masts, Yards, &c. do
Lower Deck Beams & Fastenings do Ditto ditto at other places do Sails do
Planksheers do Keelsons do Anchors, No. of Good
Sheerstrakes do Clamps and Shelves do Cables and
Topsides do Ceiling do Hawser and Warps and
Wales do Rudder do Standing and Running Rigging Sufficient
Plank (Bottom) and Counter do Copper Y.M. When put on 1870
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways
Now done. The yellow metal patched, and two new lead scuppers fitted. She is in good condition, and is in my opinion eligible to remain as classed.
Committee's Minute 13th June. 1873
Character assigned 10A1 TDW James M. Neil
Certificate (if required).