

ANNUAL SURVEYS.

33237

No. 256 Survey held at London Date 24th July - 9th Aug 1873
 on the Ship "Albuera" Master W. Thomas
 Tonnage 774 Built at Moulmeir When built 1854
 By whom built _____ Owners Millic & Sons
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Both Green's dry dock and afloat

Recd 11 3 73

[Signature]

Last Survey, No. 32932 Port of London Classed 17A1 - 12.71
 The present Condition of the
 Decks Good Treenails Good Windlass and Capstan Good
 Waterways _____ Breasthooks and Stemson _____ Pumps _____
 Comings _____ Transoms, Pointers, and Crutches _____ Boats _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Masts, Yards, &c. _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Sails Good and Sufficient
 Planksheers _____ Keelsons _____ Anchors, No. of 3 B 15. 2H.
 Sheerstrakes _____ Clamps and Shelves _____ Cables Good
 Topsides _____ Ceiling _____ Hawseers and Warps 3 and
 Wales _____ Rudder _____ Standing and Running Rigging Sufficient
 Plank (Bottom) and Counter _____ Copper As per When put on 1871
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined
The Yellow Metal, Sheathing patched and coated with patent
Composition. Is now in good and efficient condition; and
in my opinion eligible to remain as classed.
 Committee's Minute 15th Aug 73 1873 W. Thomas
 Character assigned Cour 11A IPW Certificate (if required).

No. 140 Survey held at London Date 26th July - 9th Aug 1873
 on the Ship "The Treedy" Master W. Stuart
 Tonnage 1745 Built at Combay When built 1857
 By whom built _____ Owners Millic & Sons
 Port belonging to London Destined Voyage Meerbourne
 If Surveyed Afloat or in Dry Dock Both Green's dry dock and afloat

Last Survey, No. 31907 Port of London Classed 17A1
 The present Condition of the
 Decks Good Treenails Good Windlass and Capstan Good
 Waterways _____ Breasthooks and Stemson _____ Pumps _____
 Comings _____ Transoms, Pointers, and Crutches _____ Boats _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Masts, Yards, &c. _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Sails Good and Sufficient
 Planksheers _____ Keelsons _____ Anchors, No. of 3 B 15. 2H.
 Sheerstrakes _____ Clamps and Shelves _____ Cables Good
 Topsides _____ Ceiling _____ Hawseers and Warps 3 and
 Wales _____ Rudder _____ Standing and Running Rigging Sufficient
 Plank (Bottom) and Counter _____ Copper As per When put on 1868
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined
Caulked topsides, waterway seams and around stanchions
Is now in good and efficient condition. and in
my opinion eligible to remain as classed.
 Committee's Minute 15th Aug 73 1873 W. Stuart
 Character assigned 17A IPW Certificate (if required).