

ANNUAL SURVEYS.

33319

No. 99 Survey held at London Date 14th Aug 13th Sept 1873
on the "P. Maid Marian" Master E. Richards
Tonnage 311 Built at Sunderland When built 1864-4 mo
By whom built Gifford Owners R. Rainfield
Port belonging to H.M. Destined Voyage Alcoa Bay
If Surveyed Afloat or in Dry Dock Patley Dry Dock & Victoria Dock

Last Survey, No. 32 Port of Hamburg Classed GA 1
Conty 3.5 4. 42
apl

The present Condition of the

Decks <u>Good</u>	Treenails <u>Where seen good</u>	Windlass and Capstan
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>do</u>	Sails
Planksheers <u>do</u>	Keelsons <u>do</u>	Anchors, No. of
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables
Topsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps
Wales <u>do</u>	Rudder <u>do</u>	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Y.M.</u> When put on <u>1842</u>	

General Observations and Opinion, Good
Bottom sighted. Yellow metal patched, and
scarp of stem caulked. She is in good condition, and is
in my opinion eligible to remain as classed.
Committee's Minute 19th Sept. 1873
Character assigned Good James McNeil Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion, _____
Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____
Character assigned _____



© 2021

Lloyd's Register
Foundation

Certificate (if required).

LON658 0477