

REPORT of SURVEY for REPAIRS.

33359
 1873
 6-10-73

No. in Reg. Book. 170 No. 32716 Survey held at London Date, first Survey Sep 24 Last Survey Sep 30 1873
 on the Barge "Ornate" Master Jos. Doughty
 Tonnage 438 tons built at Harwich When built 1865 - 6 mo.
 By whom built Vaux Owners J. Morrison
 Port belonging to London Destined Voyage Melbourn
 If Surveyed Afloat or in Dry Dock Bullhead Dry Dock & East India Dock
 Last Survey, No. 32716 Port London Classed 11.A.1
H.T. Low 71. 11.72

REPAIRS, &c.

Stripped yellow metal sheathing; recaulked from keel to gunwale, stanchions, and waterway seams; several bolts in knees and riders renewed with yellow metal; and resheathed bottom with yellow metal on felt.

Present Condition of the

Decks	} Good	Treenails	Good where seen	Windlass and Capstan	} Good
Waterways		Breasthooks and Stemson	do	Pumps	
Comings	} do	Transoms, Pointers, and Crutches	do	Boats	}
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	do	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} do	Ditto Ditto at other places	do	Condition, how ascertained	} and
Planksheers		Keelsons	do	Sails	
Sheerstrakes	} Good	Clamps and Shelves	do	Anchors No. of	} Sufficient
Topsides		Ceiling	do	Cables	
Wales	} do	Rudder	do	Hawsers and Warps	}
Plank (Bottom) and Counter		Copper <u>744 m.</u> When put on <u>now</u>	Bottom, Deck, & Waterways	Good	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Good	Cargo and Main Hatchways	Hatches
General Observations and Opinion,					

The vessel is now in good and efficient condition and in our opinion eligible to remain as classed.

The Amount of Entry Fee.....£..... is received by me,

Special.....

Certificate (if required) : 5 :

Committee's Minute

Character assigned

10th Oct. 1873
 11.A.1

Received by me
 J. H. Phillips



© 2021

Lloyd's Register Foundation

LN659-0010