

ANNUAL SURVEYS.

33392

Recd 25.2.74

[Signature]

No. 3 Survey held at London Date 18th February 18 74
 on the Bⁿ Lady Helen Master Robertson
 Tonnage 462 Built at Southampton When built 1864 3 mo
 By whom built Ransom Owners Ransom
 Port belonging to Southampton Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock Panama Victoria Dock and Afloat

Last Survey, No. 1491 Port of Southampton Classed 13 A1
H.T. Sou-71 11-71
 The present Condition of the
 Decks good Treenails good where seen Windlass and Capstan good
 Waterways " Breasthooks and Stemson " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings " Masts, Yards, &c. good
 Lower Deck Beams & Fastenings where seen Ditto ditto at other places " Sails "
 Planksheers " Keelsons " Anchors, No. of 3 Bows 2 Rds 1 Stm
 Sheerstrakes " Clamps and Shelves " Cables good
 Topsides " Ceiling good Hawser and Warps and
 Wales " Rudder good and efficient Standing and Running Rigging sufficient
 Plank (Bottom) and Counter " Copper patched When put on 1871-11 mo
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
Yellow metal sheathing patched and main cross
cross renewed of wood
 Committee's Minute 27th February 1874 condition and eligible to remain as
 Character assigned 13 A1 classed Viz- A1 W.B. Blaxell Certificate (if required).

No. 24 Survey held at London Date 23rd February 18 74
 on the Bⁿ Talavera Master Lantry
 Tonnage 384 Built at Humberland When built 1853
 By whom built Manning Owners Manning
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Duke Shore dry dock and Afloat

Last Survey, No. 31337 Port of Lorr. Classed 10 A1 Red
(B.L. Lon-71-79) cy 1-71
 The present Condition of the
 Decks good Treenails good where seen Windlass and Capstan good
 Waterways " Breasthooks and Stemson " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Masts, Yards, &c. now good
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
 Planksheers good where seen Keelsons " Anchors, No. of 3 Bows 2 Rds 1 Stm
 Sheerstrakes " Clamps and Shelves " Cables good
 Topsides " Ceiling " Hawser and Warps and
 Wales " Rudder good Standing and Running Rigging sufficient
 Plank (Bottom) and Counter " Copper patched When put on 1871-1 mo
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
Yellow metal sheathing patched and six new
yellow metal bolts in riders also new main lower mast
supplied
 Committee's Minute 27th February 1874 and eligible to remain as
 Character assigned A1 classed Viz- A1 Red W.B. Blaxell Certificate (if required).