

REPORT of SURVEY for REPAIRS.

33629

No. in Reg. Book. **No.** Survey held at London Date, first Survey Dec 6th Last Survey Jan'y 5th 1874
 on the Ship Hunstly Castle Master Mauly
 Tonnage 623 built at Glasgow When built 1866 - 1 mo
 By whom built Connell Owners J. Skinner
 Port belonging to Glasgow Destined Voyage Auckland
 If Surveyed Afloat or in Dry Dock Canal dry dock & J. W. India Docks

Last Survey, No. 3410 Port Glasgow Classed 14. A. 1. S.S. / M.

REPAIRS, &c.

Stripp'd off the yellow metal sheathing
 Caused from keel to gunwale.
 Resheathed with yellow metal.

Present Condition of the

Decks	<u>good</u>	Greenails	<u>Bolts where seen good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	"
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of <u>3 B. 1 S. 2 K</u>	"
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder <u>efficient</u>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	<u>When put on Now</u>	"	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of <u>good</u>	"		"
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways <u>where tested</u>	"		"
General Observations and Opinion,		Scuppers <u>good</u>	"	Cargo and Main Hatchways <u>good</u>	"
			"	Hatches <u>good</u>	"

She is now in good condition and in my opinion
 She is entitled to remain as class'd 14. A. 1.
Samuel Presions

The Amount of Entry Fee.....£ : : is received by me,

Special..... 3 : 3 :

Certificate (if required) : 5 :

Committee's Minute 17th March 18 74

Character assigned 14 A

T. B. W. 17th March



© 2021

Lloyd's Register
 Foundation

LON659-0194

Annally Castle

REPORT OF SURVEY for REPAIRS



© 2021

Lloyd's Register
Foundation