

33302

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 12 Survey held at London Date, first Survey 10 Jan^r Last Survey 31 Jan^r 1874
on the Barck's Packet Master Rowen
Tonnage 399 built at Gallion When built 1864 - 6 mo
By whom built Ed Owners Hoddington & Co
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock At H. Meens' dry dock and afloat
Last Survey, No. 3208 Port London Classed 15 A
REPAIRS, &c. H. Thon 72 1.72

This vessel was seen in the above-named dry dock on which occasion the Kelson Metal Sheathing was patched.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper	Standing & Running Rigging
Engine Room Skylights	Caulking of	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Hatches
General Observations and Opinion.	Scuppers	

Is now in good and efficient condition, and in our opinion eligible to remain as classified.

[Signature]
J. W. Blayell

The Amount of Entry Fee.....£ : : is received by me,
Special..... : :
Certificate (if required) : :

Committee's Minute 17th April 1874
Character assigned 10 A

[Signature]



© 2021
Lloyd's Register
Foundation
LON 659-0241