

# REPORT of SURVEY for REPAIRS.

33742

No. in Reg. Book. 456 No. 133276 Survey held at London Date, first Survey Apr 17<sup>th</sup> Last Survey Apr 23<sup>rd</sup> 1874.  
 on the Barque "Christine" Master H. Storey  
 Tonnage 386 built at Southwick When built 1863. - 9 mo  
 By whom built Mills Owners Hankey & Co  
 Port belonging to London Destined Voyage 2 voyage  
 If Surveyed Afloat or in Dry Dock Nelson Dock Ship.  
 Last Survey, No. 133276 Port London Classed 12 A1.  
HT69 10.53

REPAIRS, &c.

*Sighted the bottom.  
 Yellow Metal sheathing patched where necessary.*

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps <u>2 in No 82 Malattus pumps</u>	<u>Good</u>
Comings		Transoms, Pointers, and Crutches		Boats <u>3 in No</u>	<u>Good</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings		<u>Ditto Ditto at other places</u>		Condition, how ascertained <u>by Enquiry &amp; Inspection</u>	
Planksheers		Keelsons		Sails <u>2 Full Suits</u>	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 Bowers 1 1/2 in 1 1/2 in</u>	
Topsides		Ceiling		Cables <u>part seen</u>	<u>Good</u>
Wales		Rudder		Hawsers and Warps	<u>Good</u>
Plank (Bottom) and Counter		Copper <u>Good</u> When put on <u>1871</u>		Standing & Running Rigging	<u>Good</u>
Engine Room Skylights	Caulking of	Cargo and Main Hatchways	<u>Good</u>		
Coal Bunkers, Openings, Lids, &c.	Bottom, Deck, & Waterways	Hatches	<u>Good</u>		
General Observations and Opinion,	Scuppers				

*This vessel is in a good and efficient condition and eligible in my opinion to remain as Classed.*

J. Skilston.

The Amount of Entry Fee.....£..... is received by me,

Special.....

Certificate (if required).....

Committee's Minute 1<sup>st</sup> May 1874

Character assigned 12 A1

*JBW*



© 2021  
 Lloyd's Register  
 Foundation  
 LON659-0263