

33865

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey Feb<sup>r</sup> 3<sup>rd</sup> 1874 Last Survey Feb<sup>r</sup> 28<sup>th</sup> 1874  
on the S<sup>r</sup> Gualdine Master Flora  
**141** Tonnage 192 built at Grimsby When built 1871-12mo  
By whom built Radfield & Owners ~~R. & J. Radfield~~ & Thomas Weston & Co  
Port belonging to London Destined Voyage ~~Exe~~ S<sup>r</sup> Helena  
If Surveyed Afloat or in Dry Dock Atletiff cross dock & St Katharines  
Last Survey, No. 4103 Port Hull Classed 11 A 1 12 mo.

REPAIRS, &c. 1.72  
*Stripped & caulked from keel to metal line and the yellow metal renewed on felt*

Present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>TYME</u> When put on <u>now</u>	Standing & Running Rigging
Engine Room Skylights	Caulking of	Hatches
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
General Observations and Opinion,	Scuppers	
	Cargo and Main Hatchways	

*This vessel is eligible in my opinion to remain as classed A 1*

<sup>12,3</sup> The Amount of Entry Fee.....£..... is received by me, Thos. W. Brown  
Special..... 1 : 1 : - } 10.6.74  
Certificate (if required) - : - : } Thos. W. Blayell  
Committee's Minute 12<sup>th</sup> June 1874  
Character assigned 11 A 1



LON 659-0337