

REPORT of SURVEY for REPAIRS.

3389

Read 22.6.74

No. in Reg. Book. 33 No. 32 Survey held at London Date, first Survey 6th May Last Survey 2nd June 1874
on the Gk "Ocean Nymph" Master _____

Tonnage 310 built at Quebec When built 1862 (3. Mo.)

By whom built _____ Owners Hudson's Bay Company

Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Messrs Siganis' Dry Dock and Rep. Ind. Dock

Last Survey, No. 33324 Port London Classed 8. A. I.
Cont Low June 1871 - 5 yrs
(S.S. London 73 - 5 yrs)
8/73.

REPAIRS, &c.

Work done: Lighted the Bottom, overhauled the Caulking of Butts and Topsides, including the keel seams, Hoods and all the Butts. - Tarred the bottom.
The Masts, Yards and Rigging overhauled and refitted. -

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} Good.	Breasthooks and Stemson		Pumps	} Good.
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} Good.	Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places	} Good	Condition, how ascertained	} By Examination -
Planksheers		Keelsons		Sails	
Sheerstrakes	} Good.	Clamps and Shelves		Anchors	} No. of 35. 15. 216
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	} Good.
Plank (Bottom) and Counter	} Good	Copper Band &c. When put on	1865	Standing & Running Rigging	
Engine Room Skylights		Caulking of		Cargo and Main Hatchways	} Good
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	} Good	Hatches	
		Scuppers			

General Observations and Opinion,

She appeared to be in good and efficient condition, and fit, in my opinion, to remain Classed Cont A.I. from June 1871 for five years. -

The Amount of Entry Fee.....£ - : - : is received by me,
Special..... - : - : -

Certificate (if required) : :

Committee's Minute 26th June 1874

Character assigned Cover. 5 A 1

JBW

Williamson



© 2021
Lloyd's Register
Foundation