

REPORT of SURVEY for REPAIRS, &c.

3392

No. in Reg. Book. **No.** Survey held at London Date, first Survey 9th June Last Survey 23rd June 18 74
434 on the Ship Silver Eagle Master Care
 Tonnage 903 built at Thoon When built 1861-8 mo
 By whom built Portland Sh. Co. Owners Messrs. Sh. Co. Lim.
 Port belonging to London Destined Voyage New S. Wales
 If Surveyed Afloat or in Dry Dock Canal by Lock & London Locks

Last Survey, No. 33132 Port London HT-67. Years assigned, 13 Character in Register Book, A1
 5-73

REPAIRS, or EXAMINATION AS PER RULE Condition

The vessel docked on blocks, the bottom and keel sighted, and the yellow metal sheathing patched, and painted

Cause of Repairs to be clearly stated.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>So</u>	Breasthooks and Stemson	<u>So</u>	Pumps	<u>So</u>
Comings	<u>So</u>	Transoms, Pointers, and Crutches	<u>So</u>	Boats	<u>So</u>
Upper Deck Beams & Fastenings	<u>So</u>	Timbers of the Frame at the openings	<u>So</u>	Masts, Yards, &c.	<u>So</u>
Lower Deck Beams & Fastenings	<u>So</u>	Ditto Ditto at other places	<u>not seen</u>	Condition, how ascertained	<u>From Deck</u>
Planksheers	<u>So</u>	Keelsons	<u>So</u>	Sails	<u>Good</u>
Sheerstrakes	<u>So</u>	Clamps and Shelves	<u>Good</u>	Anchors No. of	<u>3 B - 18th 2 K</u>
Topsides	<u>So</u>	Ceiling	<u>So</u>	Cables	<u>Good</u>
Wales	<u>So</u>	Rudder	<u>Good and efficient</u>	Hawsers and Warps	<u>and</u>
Plank (Bottom) and Counter	<u>not seen</u>	Copper	<u>Y. M. F. When put on 1873</u>	Standing & Running Rigging	<u>sufficient</u>
Engine Room Skylights	<u>Coal Bunker, Openings, Lids, &c.</u>	Caulking of	<u>Bottom, Deck, & Waterways</u>	Cargo and Main Hatchways	<u>Good</u>
General Observations, Opinion as to Class, &c.	<u>She is now in good and efficient condition and fit in my opinion for the safe conveyance of dry and perishable goods to and from all parts of the world and eligible to continue as classed.</u>	Scuppers	<u>Good</u>	Hatches	<u>Good</u>

viz- 13 A1. untill June 1875, in accordance with Rules.

The Amount of Entry Fee£ : : received by me }
 Special£ : : 187
 Certificate (if required)£ : : 5/- not paid
 (Travelling Expenses, if any, £)

Committee's Minute 3rd July 1874
 Character assigned 13 A1

Thomas W Blarell
 Surveyor to Lloyd's Register of British and Foreign Shipping.

[4,000-30/5/74.]

TBW



© 2021
 Lloyd's Register
 Foundation

LON659-0374