

No. in Reg. Book. on the *475* Survey held at *London* Date, first Survey *27 Jun 7* Last Survey *8 Feb 74* 18*75*  
*L. Dinphale Castle* Master *Hilder* *34465*

Tonnage *644.33* Built at *Sunderland* When built *1861. 9 mo*  
By whom built *Long* Owners *Alan*  
Port belonging to *London* Destined Voyage *-*

If Surveyed Afloat or in Dry Dock *Dry dock*  
Last Survey, No. *33757* Port of *London* Classified *140A*  
Years assigned. *4.74* Character in Register Book. *H.T. 64.*

Present Condition of the Decks *(Good)* Treenails *(Good)*  
Waterways *(Good)* Breasthooks and Stemson *(Good)*  
Comings *(Good)* Transoms, Pointers, and Crutches *(Good)*  
Upper Deck Beams & Fastenings *(Good)* Timbers of the Frame at the Openings *(Good)*  
Lower Deck Beams & Fastenings *(Good)* Ditto ditto at other places *(Good)*  
Planksheers *(Good)* Keelsons *(Good)*  
Sheerstrakes *(Good)* Clamps and Shelves *(Good)*  
Topsides *(Good)* Ceiling *(Good)*  
Wales *(Good)* Rudder *(Good)*  
Plank (Bottom) and Counter *(Good)* Copper on Y.M. *(Good)* When put on *74*  
Engine Room Skylights *(Good)* Coal Bunkers, Openings, Lids, &c. *(Good)* Scuppers *(Good)* Cargo and Main Hatchways *(Good)* Hatches *(Good)*  
General Observations, Opinion as to Class, &c. *(Good)*

*Rudder unhung and one pintle recast.*  
*The ship appears in good condition and eligible to remain as classed.*

Committee's Minute *19th February* 18*75*  
Character assigned *14A*  
Surveyor to Lloyd's Register of British and Foreign Shipping. *W. Congdon*  
Certificate (if required) *PAID* 18  
*JPW*