

Paid 34644

No. 411 Survey held at London Date, first Survey 24 April Last Survey 24 April 1875
 on the "L. Vincelles" Master _____
 Tonnage 904 Built at Moulmein When built 1858
 By whom built Dunbar Owners Allan
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock dry dock

Last Survey, No. 33644 Port of London Classed 15-A 3-74-5 yr
 Character in Register Book. Cont 73-5 yr

Present Condition of the Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>Two</u> <u>de</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>Five</u> <u>de</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.	<u>de</u>
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained	<u>de</u>
Planksheers	Keelsons	Sails	<u>well found</u> <u>de</u>
Sheerstrakes	Clamps and Shelves	Anchors, No. of	<u>383</u> <u>17</u> <u>8</u> <u>the</u> <u>de</u>
Top-sides	Ceiling	Cables	<u>complete</u>
Wales	Rudder	Hawsers and Warps	<u>suff</u> <u>5</u>
Plank (Bottom) and Counter	Copper or Y.M. When put on	Standing and Running Rigging	<u>good</u>
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Scuppers	<u>Good</u>
General Observations, Opinion as to Class, &c.	Coal Bunkers, Openings, Lids, &c.	Cargo and Main Hatchways	<u>Good</u>
		Hatches	<u>Good</u>

This ship appears in good condition and eligible to remain as classed.

Committee's Minute 30th April 1875.
 Character assigned Cont 5
 Surveyor to Lloyd's Register of British and Foreign Shipping. Ho. Poulton
 Certificate (if required) _____ Paid _____ 18 _____

Lucelles

Dr. William Wallace



© 2021

Lloyd's Register
Foundation