

# ANNUAL SURVEYS.

34746 ~~24661~~

Paid 14.6.75

No. in Reg. Book. 292 on the Ship Bentonion Survey held at London Date, first Survey \_\_\_\_\_ Last Survey June 12 1875

Tonnage 424 Built at Aberdeen When built 1869 4M Master \_\_\_\_\_

By whom built Hood Owners G. Thompson Junr

Port belonging to Aberdeen Destined Voyage \_\_\_\_\_

If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 324016 Port of London Classed 12A/ 3.74

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Condition, how ascertained	<u>and</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>Sufficient</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors, No. of <u>3 Ben &amp; 1 Reg</u>	<u>where</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables	<u>they</u>
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>could be</u>
Plank (Bottom) and Counter	<u>"</u>	Copper or Y.M.	<u>When put on 1874</u>	Standing and Running Rigging	<u>seen</u>
Engine Room Skylights	<u>"</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>"</u>	Scuppers	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. She is now in an efficient state of repair and entitled to remain as classed

Committee's Minute 18th June 1875 12A/

Character assigned 12A/

Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18

Sewhouse Martindale

No. in Reg. Book. 544 on the S Shannon Survey held at London Date, first Survey \_\_\_\_\_ Last Survey May 27 1875

Tonnage 544 Built at London When built 1862 5 mo. Master \_\_\_\_\_

By whom built Green Owners R. H. Green Wens

Port belonging to London Destined Voyage Australia

If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 324013 Port of London Classed 14A/ 8.74

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Pumps	
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>	Condition, how ascertained	<u>and</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Sails	<u>Sufficient</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	Anchors, No. of <u>3 Ben &amp; 1 Reg</u>	<u>where</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>	Cables	<u>they</u>
Wales	<u>do</u>	Rudder	<u>do</u>	Hawsers and Warps	<u>could</u>
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M.	<u>When put on 1874</u>	Standing and Running Rigging	<u>be seen</u>
Engine Room Skylights	<u>"</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>"</u>	Scuppers	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. She is now in an efficient state of repair and entitled to remain as classed

Committee's Minute 18th June 1875 14A/

Character assigned 14A/

Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18

Sewhouse Martindale