

# ANNUAL SURVEYS.

34,783

No. in Reg. Book. **202** **216** No. **34258** Survey held at London Date, first Survey 28 June Last Survey 28 June 1875  
 on the S. L. Armer the ship Master Jenkins  
 Tonnage 812 Built at P. Dock When built 1865 6 mo.  
 By whom built Long Owners Jenkins  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 34258 Port of London Classed 14 ST 4-74  
 Character in Register Book H.T. 72  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_  
 Comings \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_  
 Planksheers \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_  
 Topsides \_\_\_\_\_  
 Wales \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_  
 Coal Bunker, Openings, Lids, &c. \_\_\_\_\_  
 Scuppers \_\_\_\_\_  
 Cargo and Main Hatchways \_\_\_\_\_  
 Hatches \_\_\_\_\_  
 Treenails \_\_\_\_\_  
 Breasthooks and Stemson \_\_\_\_\_  
 Transoms, Pointers, and Crutches \_\_\_\_\_  
 Timbers of the Frame at the Openings \_\_\_\_\_  
 Ditto ditto at other places \_\_\_\_\_  
 Keelsons \_\_\_\_\_  
 Clamps and Shelves \_\_\_\_\_  
 Ceiling \_\_\_\_\_  
 Rudder \_\_\_\_\_  
 Copper on Y.M. \_\_\_\_\_ When put on 74  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Windlass and Capstan \_\_\_\_\_  
 Pumps \_\_\_\_\_  
 Boats \_\_\_\_\_  
 Masts, Yards, &c. \_\_\_\_\_  
 Condition, how ascertained \_\_\_\_\_  
 Sails \_\_\_\_\_  
 Anchors, No. of \_\_\_\_\_  
 Cables \_\_\_\_\_  
 Hawseers and Warps \_\_\_\_\_  
 Standing and Running Rigging \_\_\_\_\_

General Observations, Opinion as to Class, &c. This vessel appears in good condition and eligible to remain as classed.

Surveyed with large quantity of ballast in hold.

Committee's Minute 2nd July 1875 Thos Congdon  
 Character assigned 14A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. in Reg. Book. 476 1006 No. \_\_\_\_\_ Survey held at London Date, first Survey 28 June Last Survey 28 June 1875  
 on the Bonnie Stranah Master \_\_\_\_\_  
 Tonnage 449 Built at Sunderland When built 1866 5 mo.  
 By whom built Gardner Owner A. Walker  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 33995 Port of London Classed 11 ST 7-74  
 Character in Register Book \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_  
 Comings \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_  
 Planksheers \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_  
 Topsides \_\_\_\_\_  
 Wales \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_  
 Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_  
 Scuppers \_\_\_\_\_  
 Cargo and Main Hatchways \_\_\_\_\_  
 Hatches \_\_\_\_\_  
 Treenails \_\_\_\_\_  
 Breasthooks and Stemson \_\_\_\_\_  
 Transoms, Pointers, and Crutches \_\_\_\_\_  
 Timbers of the Frame at the Openings \_\_\_\_\_  
 Ditto ditto at other places \_\_\_\_\_  
 Keelsons \_\_\_\_\_  
 Clamps and Shelves \_\_\_\_\_  
 Ceiling \_\_\_\_\_  
 Rudder \_\_\_\_\_  
 Copper on Y.M. \_\_\_\_\_ When put on 74  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Windlass and Capstan \_\_\_\_\_  
 Pumps \_\_\_\_\_  
 Boats \_\_\_\_\_  
 Masts, Yards, &c. \_\_\_\_\_  
 Condition, how ascertained \_\_\_\_\_  
 Sails \_\_\_\_\_  
 Anchors, No. of \_\_\_\_\_  
 Cables \_\_\_\_\_  
 Hawseers and Warps \_\_\_\_\_  
 Standing and Running Rigging \_\_\_\_\_

General Observations, Opinion as to Class, &c. This vessel appears in good condition and eligible to remain as classed.

Committee's Minute 2nd July 1875 Thos Congdon  
 Character assigned 14A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

