

ANNUAL SURVEYS.

35,242

No. in Reg. Book. on the **No. 51** Survey held at London Date, first Survey 21 Jan 74 Last Survey 21 January 1876
 Tonnage 639 Built at Hunderland When built 1853
 By whom built _____ Owners Alan
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 34336 Port of London Classed 14 Years assigned 12-74 Character in Register Book. Complete and efficient

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____
Coal Bunker, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

General Observations, Opinion as to Class, &c. Examined inside and outside where practicable and found good. The ship appears eligible to remain as classed. Surveyed with part cargo on board. This vessel has been in dry dock but not seen by me there, being at Deptford.

Committee's Minute 28 January 1876 John Congdon
 Character assigned Class G
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned _____ Character in Register Book. _____

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



9600-19907