

REPORT of SURVEY for REPAIRS, &c.

33.3 79
(Recd 20-3-76)

No. in Reg. Book. **No.** Survey held at London Date, first Survey March 3 Last Survey March 17 1876

232 on the S Whiteadder Master Betham

TONNAGE under Tonnage Deck <u>844.52</u>	Built at <u>London</u>	When built <u>1862</u>	YEAR. MONTH.
Ditto of Spar Deck, or Avoing Deck <u>70.12</u>	Owners <u>Williston</u>	Port belonging to <u>London</u>	
Ditto of Poop, or Raised Qr. Dk.	Residence	By whom built <u>Bilbe</u>	Destined Voyage <u>Japan</u>
Ditto of Houses on Deck		If Surveyed Afloat or in Dry Dock <u>Dry Dock</u>	
Ditto of Forecastle			
Gross Tonnage <u>914.64</u>			
Crew Space, as per Rule			
Register Tonnage, cut on Beam <u>914.64</u>			
Engine Room			
Reg. Tons as St'mer, cut on Bm.			

Length of Poop 35 ft. Ditto, Forecastle 38 ft. Ditto, Raised Quarter Deck 7 ft. Years assigned. 12 A 7 74
Last Survey, No. 34061 Port London (BS) Classed 12 A 7 74
but see June 76 8 years

REPAIRS, OR EXAMINATION AS PER RULE

At the present time the Yellow Metal shipped caulked from keel to top of Wales and Re Yellow Metalled on plating to same height. Owing to being worn one plank in the flat of bottom on the starboard side shipped with Am Rock Elm.

Repairs to be clearly stated.

328	Condition of the	Good	Treenails	Good	Windlass and Capstan	
	De Eng.		Breasthooks and Stemson	"	Pumps	
	Wo Reg.		Transoms, Pointers, and Crutches	"	Boats	
			Timbers of the Frame at the openings	"	Masts, Yards, &c.	Good
	Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	and
	Deck Beams & Fastenings	"	Keelsons	"	Sails	Sufficient
	Planksheers	"	Clamps and Shelves	"	Anchors No. of 3 Br. 12 1/2 inch	where
	Sheerstrakes	"	Ceiling	"	Cables	they
	Topsides	"	Rudder	"	Hawsers and Warps	could be
	Wales	"	Copper Y Metal on When put on	Now	Standing & Running Rigging	seen
	Plank (Bottom) and Counter	"	Caulking of			
	Engine Room Skylights	"	Bottom, Deck, & Waterways	Good	Cargo and Main Hatchways	Good
	Coal Bunker, Openings, Lids, &c.	"	Scuppers	Good	Hatches	Good

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martindale

The Amount of Entry Fee ... £ 2 : 2 : received by me, AB
Special ... £ 2 : 2 : 21 Mar 1876
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)

Committee's Minute 14th April 1876

Character assigned Cour 8 A
TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021
Lloyd's Register
Foundation