

ANNUAL SURVEYS.

38.380

14th Dec 30.3.76

No. in Reg. Book. on the 234 No. 1 Survey held at London Date, first Survey 14th March Last Survey 14th March 1876
 Tonnage 960 Built at Shields Master — When built 1856
 By whom built — Owners Harprow &
 Port belonging to Spool Destined Voyage —
 If Surveyed Afloat or in Dry Dock Linthouse dock

Last Survey, No. 34343 Port of London

Classed 13 Years assigned. 13 Character in Register Book. 3.75

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>—</u>
Waterways <u>de</u>	Breasthooks and Stemson <u>de</u>	Pumps <u>—</u>
Comings <u>de</u>	Transoms, Pointers, and Crutches <u>de</u>	Boats <u>—</u>
Upper Deck Beams & Fastenings <u>de</u>	Timbers of the Frame at the Openings <u>de</u>	Masts, Yards, &c. <u>—</u>
Lower Deck Beams & Fastenings <u>de</u>	Ditto ditto at other places <u>de</u>	Condition, how ascertained <u>and</u>
Planksheers <u>de</u>	Keelsons <u>where seen</u>	Sails <u>—</u>
Sheerstrakes <u>de</u>	Clamps and Shelves <u>de</u>	Anchors, No. of <u>—</u>
Topsides <u>de</u>	Ceiling <u>where seen</u>	Cables <u>—</u>
Wales <u>de</u>	Rudder <u>de</u>	Hawsers and Warps <u>—</u>
Plank (Bottom) and Counter <u>where seen</u>	Copper or Y.M. <u>—</u> When put on <u>175</u>	Standing and Running Rigging <u>—</u>
Engine Room Skylights <u>—</u>	Caulking of <u>—</u>	Cargo and Main Hatchways <u>—</u>
Coal Bunker, Openings, Lids, &c. <u>—</u>	Bottom, Deck, & Waterways <u>Good</u>	Hatches <u>—</u>
General Observations, Opinion as to Class, &c. <u>—</u>	Scuppers <u>—</u>	

This Vessel appears in good Condition and eligible to remain as classed.

Surveyed with Ballast in main hold

Committee's Minute 4th April 1876 Thos. Congdon
 Character assigned Good 9A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18—


No. — Survey held at — Date, first Survey — Last Survey — 18—
 No. in Reg. Book. on the — Master —
 Tonnage — Built at — When built —
 By whom built — Owners —
 Port belonging to — Destined Voyage —
 If Surveyed Afloat or in Dry Dock —

Last Survey, No. — Port of — Classed — Years assigned. — Character in Register Book. —

Present Condition of the	Treenails	Windlass and Capstan
Decks	Breasthooks and Stemson	Pumps
Waterways	Transoms, Pointers, and Crutches	Boats
Comings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Upper Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors, No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper or Y.M. <u>—</u> When put on <u>—</u>	Standing and Running Rigging
Plank (Bottom) and Counter	Caulking of <u>—</u>	Cargo and Main Hatchways
Engine Room Skylights	Bottom, Deck, & Waterways	Hatches
Coal Bunkers, Openings, Lids, &c.	Scuppers	
General Observations, Opinion as to Class, &c.		

Committee's Minute — 18—

Character assigned —
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18—



© 2021

Lloyd's Register Foundation

110-1960

Mertrude



© 2021

Lloyd's Register
Foundation