

# ANNUAL SURVEYS.

35381

No. in Reg. Book. **292** No. **1316** Survey held at **London** Date, first Survey **28<sup>th</sup> Feb** Last Survey **25<sup>th</sup> March** 18**76**  
 on the **"Lelia Alice"** Master **Weir**  
 Tonnage **309** Built at **P. E. Harland** When built **1869-4**  
 By whom built **Hagden** Owners **Lomas Weston & Co.**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Globe by dock**

Last Survey, No. **33603** Port of **London**  
 Present Condition of the Decks **Good** Treennails **Good**  
 Waterways **"** Breasthooks and Stemson **"**  
 Comings **"** Transoms, Pointers, and Crutches **"**  
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**  
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**  
 Planksheers **"** Keelsons **"**  
 Sheerstrakes **"** Clamps and Shelves **"**  
 Topsides **"** Ceiling **"**  
 Wales **"** Rudder **"**  
 Plank (Bottom) and Counter **"** Copper or Y.M. on felt When put on **74**  
 Engine Room Skylights **"** Caulking of Bottom, Deck, & Waterways **Good**  
 Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Bottom sighted and the yellow metal sheathing patched, fore topmast new of Pitch Pine,**

This Vessel is now in good and efficient condition and eligible to remain as classed.  
 Committee's Minute **4<sup>th</sup> April** 18**76** **Thos W. Blagell.**  
 Character assigned **8A1** **JRM** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** 18

No. in Reg. Book. **87** No. **1317** Survey held at **London** Date, first Survey **10<sup>th</sup> March** Last Survey **11<sup>th</sup> March** 18**76**  
 on the **"Maggie"** Master **Adams**  
 Tonnage **161** Built at **Radford Bideford** When built **1870-10 mo**  
 By whom built **Cox** Owners **J. Brodie**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Globe by dock**

Last Survey, No. **33344** Port of **London**  
 Present Condition of the Decks **Good** Treennails **Good**  
 Waterways **"** Breasthooks and Stemson **"**  
 Comings **"** Transoms, Pointers, and Crutches **"**  
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**  
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**  
 Planksheers **"** Keelsons **"**  
 Sheerstrakes **"** Clamps and Shelves **"**  
 Topsides **"** Ceiling **"**  
 Wales **"** Rudder **"**  
 Plank (Bottom) and Counter **"** Copper or Y.M. on felt When put on **73**  
 Engine Room Skylights **"** Caulking of Bottom, Deck, & Waterways **Good**  
 Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Bottom sighted and the yellow metal sheathing patched.**

This Vessel is now in good and efficient condition and eligible to remain as classed.  
 Committee's Minute **4<sup>th</sup> April** 18**76** **Thos W. Blagell.**  
 Character assigned **12A1** **JRM** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** 18