

REPORT of SURVEY for REPAIRS, &c.

35494

(Re 26.5.76)

No. in Reg. Book. **No.** Survey held at London Date, first Survey 15th May Last Survey 20th May 1876
6923 on the Ship "Brundaleer" Master J Hunter
 Tonnage under Tonnage Deck 824 Built at Aberdeen When built 1869 3
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 937
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 921
 Engine Room
 Reg. Tons as St^rmer, cut on Bm.

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. 10 Character in Register Book. A.1.
 Last Survey, No. 35417 Port London H. I. Lon 7 1/2 14. 76

REPAIRS, OR EXAMINATION AS PER RULE

Now added since the last Report on the above Vessel; Inner waterways of Pitch Pine 14x14" extending from two beams within forecastle abaft mainmast fastened with through galvanized Iron Bolts in every timber; two strong Iron Knees fitted at each end of main Hatchway connecting the fore & aft Carlings to beams.

Present Condition of the			
Decks	<u>Good</u>	Treenails	<u>Good</u>
Waterways	<u>—</u>	Breasthooks and Stemson	<u>—</u>
Comings	<u>—</u>	Transoms, Pointers, and Crutches	<u>—</u>
Upper Deck Beams & Fastenings	<u>—</u>	Timbers of the Frame at the openings	<u>—</u>
Lower Deck Beams & Fastenings	<u>—</u>	Ditto Ditto at other places	<u>—</u>
Planksheers	<u>—</u>	Keelsons	<u>—</u>
Sheerstrakes	<u>—</u>	Clamps and Shelves	<u>—</u>
Topsides	<u>—</u>	Ceiling	<u>—</u>
Wales	<u>—</u>	Rudder	<u>—</u>
Plank (Bottom) and Counter	<u>—</u>	Copper <u>galv</u> When put on <u>now</u>	
Engine Room Skylights	<u>—</u>	Caulking of	
Coal Bunker, Openings, Lids, &c.	<u>—</u>	Bottom, Deck, & Waterways	<u>Good</u>
General Observations, Opinion as to Class, &c.	This Vessel is now in good and efficient condition and eligible to remain as classed; viz. 10 A.1.		
		Windlass and Capstan	<u>Good</u>
		Pumps	<u>—</u>
		Boats	<u>—</u>
		Masts, Yards, &c.	<u>—</u>
		Condition, how ascertained	<u>from deck</u>
		Sails	<u>Good</u>
		Anchors No. of	<u>3 Nos 18 lb 2 1/2</u>
		Cables	<u>Good</u>
		Hawsers and Warps	<u>and</u>
		Standing & Running Rigging	<u>sufficient</u>
		Cargo and Main Hatchways	<u>Good</u>
		Hatches	<u>Good</u>

The Amount of Entry Fee ... £ ...
 Special ... £ 2 : 2 :
 Certificate (if required) ... £ : 5 :
 (Travelling Expenses, if any, £ ...)
 Committee's Minute 30th May 1876
 Character assigned 10 A.1

received by me, W. C. Davey 30 May 1876

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LDN661-0241

[3,000-1/11/75.] (The Surveyors are requested not to write on or below the space for Committee's Minute.)