

REPORT of SURVEY for REPAIRS, &c.

* 35,516

(Rec 13.6.76)

No. in Reg. Book. **No.** 561 on the *BR Prince of Wales* Survey held at *London* Date, first Survey *May 6* Last Survey *June 7* 18*76*

Master _____
 Tonnage under Tonnage Deck *475*
 Ditto of Spar Deck, or Avning Deck _____
 Ditto of Poop, or Raised Qr. Dk. _____
 Ditto of Houses on Deck _____
 Ditto of Forecastle _____
 Gross Tonnage *507*
 Crew Space, as per Rule _____
 Register Tonnage, cut on Beam *507*
 Engine Room _____
 Reg. Tons as St' mer, cut on Bm. _____
 Built at *Southampton* When built *1850*
 Owners *Hudson Bay Co* Port belonging to *London*
 Residence _____
 By whom built _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Dry Dock*

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft.
 Last Survey, No. *34282* Port *London*
 Classed *15A1 11/74* *Gen 165-10 yrs HT 68* *Expiry*

REPAIRS, OR EXAMINATION AS PER RULE

At the present time this vessel came into Dry Dock had her Yellow Metal stripped off and bulkhead from keel to gunwale and has had iron plates fitted on the Stern & Poors as a protection in the Ice.

The Manager Capt Ford was informed that the time of her stay had run out. No order for survey was given.

Senhouse Martinide

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		Hatches
Cargo and Main Hatchways		

General Observations, Opinion as to Class, &c. _____

The Amount of Entry Fee ... £ : : received by me, }
 Special ... £ : : 187 }
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LONG61-0257

Cause of Repairs to be clearly stated.

reg. No. 13,000-8/133