

ANNUAL SURVEYS.

35,577

Recd 8.7.76

No. in Reg. Book. on the **No. 229** Ship **"Sevana"** Survey held at **London** Date, first Survey **14th June** Last Survey **14th June 1876** Master **H. May**
 Tonnage **795** Built at **Aberdeen** When built **1864 - 11 mo**
 By whom built **Hall** Owners **Jamieson & Co**
 Port belonging to **Aberdeen** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Horseferry by dock**

Last Survey, No. **34850** Port of **London** Classed **13** Years assigned. **7-75** Character in Register Book. **A.1.**
 Present Condition of the Decks **Good** Treennails **Good**
 Waterways **Good** Breasthooks and Stemson **Good**
 Comings **Good** Transoms, Pointers, and Crutches **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
 Planksheers **Good** Keelsons **Good**
 Sheerstrakes **Good** Clamps and Shelves **Good**
 Topsides **Good** Ceiling **Good**
 Wales **Good** Rudder **Good**
 Plank (Bottom) and Counter **Good** Copper or Y.M. on felt When put on **1875**
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Bottom sighted and the yellow metal sheathing patched, several broken throat bolts in knees taken out and renewed a size larger.**
This Vessel is now in good and efficient condition and eligible to remain as classed.

Committee's Minute **13th July** 1876
 Character assigned **13 A.1.**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **5th July 1876**

No. in Reg. Book. on the **No. 213** Ship **"Maori"** Survey held at **London** Date, first Survey **20th June** Last Survey **20th June 1876** Master **Sim**
 Tonnage **799** Built at **Sunderland** When built **1851**
 By whom built **G Traill & Sons**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Princes by dock**

Last Survey, No. **24605** Port of **Liverpool** Classed **14** Years assigned. **5-75** Character in Register Book. **A.1.**
 Present Condition of the Decks **Good** Treennails **Good**
 Waterways **Good** Breasthooks and Stemson **Good**
 Comings **Good** Transoms, Pointers, and Crutches **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
 Planksheers **Good** Keelsons **Good**
 Sheerstrakes **Good** Clamps and Shelves **Good**
 Topsides **Good** Ceiling **Good**
 Wales **Good** Rudder **Good**
 Plank (Bottom) and Counter **Good** Copper or Y.M. on felt When put on **75**
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **This Vessel is now in good and efficient condition and eligible to remain as classed.**

Committee's Minute **13th July** 1876
 Character assigned **14 A.1.**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **5th July 1876**