

ANNUAL SURVEYS.

33661

No. in Reg. Book. **236** No. **134** Survey held at **London** Date, first Survey **Aug 29** 1876 Last Survey **Aug 29** 1876
 on the **134 Olga** Master **Stankov**
 Tonnage **431** Built at **Sunderland** When built **1866** 1 M
 By whom built **Mills** Owners **Stankov**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **34608** Port of **London** Classed **1341 4.75**
 Years assigned. **HT 10.71** Character in Register Book.
 Present Condition of the
 Decks **Good** Treennails **Good**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. When put on **1874**
 Caulking of **Patched now**
 Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **"** Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair & entitled to remain as classed

Senhouse Martineau

Committee's Minute **18th August 1876**

Character assigned **1341**

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18

No. in Reg. Book. **952** No. **5** Survey held at **London** Date, first Survey **Aug 22** 1876 Last Survey **Aug 22** 1876
 on the **S Collingrove (Composite)** Master **Sanderson**
 Tonnage **861** Built at **Sunderland** When built **1869** 7 mo.
 By whom built **Jas Laing** Owners **A L Elder**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **34182** Port of **London** Classed **1604 10.74**
 Years assigned. **SS 10.74** Character in Register Book.
 Present Condition of the
 Decks **Good** Treennails **Good**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. When put on **1874**
 Caulking of **Patched now**
 Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **"** Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martineau

Committee's Minute **18th August 1876**

Character assigned **1604**

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18