

ANNUAL SURVEYS.

No. in Reg. Book. 443 No. 1874 Survey held at LONDON Date, first Survey 29 Aug Last Survey 29 August 1876
 on the "Elizabeth Mary" Master Riddell
 Tonnage 262 Built at Sunderland When built 1866 4 mo
 By whom built Watson Owners J. Duncan
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Hutchinson dock

Last Survey, No. 34114 Port of London
 Present Condition of the Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter
 Engine Room Skylights
 Coal Bunker, Openings, Lids, &c.
 General Observations, Opinion as to Class, &c.
 Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings
 Ditto ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper or Y.M.
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of
 Cables
 Hawser and Warps
 Standing and Running Rigging
 Hatches

This vessel appears in good condition and eligible to remain as classed.

Committee's Minute 26 September 1876
 Character assigned 11A

Thos Congdon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. 672 No. 1875 Survey held at London Date, first Survey 15 Sept Last Survey 8 Sept 1876
 on the "Sir Harry Parkes" Master
 Tonnage 807 Built at Sunderland When built 1863 4 mo
 By whom built Briggs Owners Shepherd
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Greenwich dry dock

Last Survey, No. 34846 Port of London
 Present Condition of the Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter
 Engine Room Skylights
 Coal Bunkers, Openings, Lids, &c.
 General Observations, Opinion as to Class, &c.
 Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings
 Ditto ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper or Y.M.
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of
 Cables
 Hawser and Warps
 Standing and Running Rigging
 Hatches

This vessel appears in good condition and eligible to remain as classed.

Surveyed with part outward cargo on board.

Committee's Minute 26 September 1876
 Character assigned 15A

Thos Congdon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18