

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** 477 on the **Bⁿ "Marseilles"** Survey held at **London** Date, first Survey **26 Sept** Last Survey **29 Sept** 18**76** Master **Gill**

TONNAGE under Tonnage Deck **1811.08** Built at **St. Brnsⁿ** When built **1856**
 Ditto of Spar Deck, or Awning Deck **76.48** Owners **R. G. Soumerville** Port belonging to **Port Glasgow**
 Ditto of Poop **18.66** Residence **R Glasgow**
 Ditto of Raised Qr. Dk. **1106.22** By whom built **Destined Voyage**
 Ditto of Houses on Deck **36.67** If Surveyed Afloat or in Dry Dock **Line Kln Dock**
 Gross Tonnage **1069.55**
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St^rmer, cut on Bm.

Length of Poop **47.6** ft. Ditto, Forecastle **34** ft. Ditto, Raised Quarter Deck **7** ft. Years assigned **7** Character in Register Book **At red 1074**
 Dimensions **188.5 x 57 x 22.25** Classed **d/2** **S.S. Cly 12-54**
 Last Survey, No. **6643** Port **Glyde**

REPAIRS, OR EXAMINATION AS PER RULE

Yellow Metal stripped off. Caulked from Keel to Waler, and part of upper works Caulked at the after end. Re installed over felt as before.

Surveyed with ballast in Hold.

Present Condition of the

| | | |
|----------------------------------|---|---------------------------------------|
| Decks | Treenails <i>where seen</i> Good | Windlass and Capstan |
| Waterways | Breasthooks and Stemson dc dc | Pumps |
| Comings | Transoms, Pointers, and Crutches dc dc | Boats Good |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the opening dc dc | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places dc dc | Condition, how ascertained and |
| Planksheers Good | Keelsons dc dc | Sails |
| Sheerstrakes | Clamps and Shelves dc dc | Anchors No. of Complete |
| Topsides | Ceiling dc dc | Cables |
| Wales | Rudder dc dc | Hawsers and Warps |
| Plank (Bottom) and Counter | Copper Y. M. When put on Sep^r 1/76 | Standing & Running Rigging |
| Engine Room Skylights | Caiking of | |
| Coal Bunker, Openings, Lids, &c. | Bottom, Deck, & Waterways Good | |
| Scuppers | | |
| Cargo and Main Hatchways | | |
| Hatches | | |

General Observations, Opinion as to Class, &c.

This vessel appears in good condition and eligible to remain as classed.

The Amount of Entry Fee ... £ ... received by me, **W. H. Congdon**

9/10/76 Special ... £ 3 : 3 : 13th 1876

Certificate (if required) ... £ : : :

avelling Expenses, if any, £

Committee's Minute **13th October 1876**

Character assigned **At red**

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON661-0411

Marcellis



© 2021

Lloyd's Register
Foundation