

35,813

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at London Date, first Survey 2 Dec^r Last Survey 6 Dec^r 1876
Master J. Lightelm

437 on the Linelles
TONNAGE under Tonnage Deck 798 Built at Amulmen When built 1858
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Deck
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 892 Owners Manly Port belonging to London
Crew Space, as per Rule
Register Tonnage, cut on Beam 892 By whom built Dunbar Destined Voyage
Engine Room If Surveyed Afloat or in Dry Dock Linelles dock
Reg. Tons as St^rmer, cut on Bm.
Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft.
Classed 15 Years assigned. 5.45 Character in Register Book.
Last Survey, No. 34693 Port London Coal 54p

REPAIRS, OR EXAMINATION AS PER RULE
Yellow metal stripped off Bottom cleaned down. Caulked from keel to the upper part of wales, also the three upper strakes and all the putts Caulked. Yellow metalled over felt as before.
Surveyed with part cargo on board

Present Condition of the Decks	Treenails <u>when seen good</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson <u>do do</u>	Pumps
Comings	Transoms, Pointers, and Crutches <u>do do</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings <u>do do</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>good</u>	Ditto Ditto at other places <u>do do</u>	Condition, how ascertained
Plank sheers	Keelsons <u>do do</u>	Sails
Sheerstrakes	Clamps and Shelves <u>do do</u>	Anchors No. of <u>and</u>
Topsides	Ceiling <u>do do</u>	Cables
Wales	Rudder <u>do do</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Y. M. When put on Dec^r 1876</u>	Standing & Running Rigging <u>complete</u>
Engine Room Skylights	Caulking of	Cargo and Main Hatchways <u>Hatches</u>
General Observations, Opinion as to Class, &c.	Bottom, Deck, & Waterways	
	Coal Bunker, Openings, Lids, &c.	
	Scuppers	

This ship appears in good condition and eligible to remain as classed.

The Amount of Entry Fee ... £ 2 : 25 : received by me, J. M. Conydon
Certificate (if required) ... £ 2 : 25 :
(Travelling Expenses, if any, £)
Committee's Minute 15th December 1876
Character assigned Coal 54p
J. M. Conydon
Surveyor to Lloyd's Register of British and Foreign Shipping.



[S. 000-21/176.] The Surveyors are requested not to write on or below the space for Committee's Minute.

Incels



© 2021

Lloyd's Register
Foundation

MEMBER OF THE LLOYD'S REGISTER GROUP